© Crown copyright and database rights 2018 Ordnance Survey 0100031673
© Local Government Information House Limited copyright and database rights 2019 Ordnance Survey 0100031673

SURVEY BOUNDARY

LOWER END

AREA OF WALL RECENTLY RENOVATED

DRY STONE WALL 0.5M IN GOOD CONDITION

1.2m NATURAL STONE WALLING

EARTH BANKED UP TO BELOW COPING OF WALL

WALL BUCKLES OUTWARDS SLIGHTLY DUE TO TREE ROOTS

St Michael and All Angels' Church

Cross

1.2m NATURAL STONE WALLING

AREA OF OVERHANGING VEGETATION

METAL PEDESTRIAN GATE AND WOODEN POSTS IN GOOD CONDITION

LOCATION OF ECO LOO

Lych Gate

GRAVEL PATHWAYS NEED SOME MAINTENANCE AND ATTENTION TO ENCROACHING VEGETATION ALONG KERBING

0.8m NATURAL STONE WALLING GOOD CONDITION

SUBSIDENCE CRACKS ON STONE WALLING CONNECTING TO BOTH SIDES OF LYCH GATE. NOT DEEMED UNSTABLE.

LYCH GATE WOODEN STRUCTURAL SUPPORTS IN POOR CONDITION ON BOTH SIDES. WOOD DECAY IN LOWER SECTIONS OF BASE WHERE CONNECTS TO PLINTH WOODEN FENCE LOWER SECTIONS DECAYED AND NEED REPLACING.

AREA OF WALL RECENTLY RENOVATED

Overgrown

1.2m NATURAL STONE WALLING

AREA OF WALLING BUCKLING IN TOWARDS CEMETERY HOWEVER IN GOOD STABLE CONDITION

EARTH BANKED UP TO BELOW COPING OF WALL

CONCRETE PATHWAY IN GOOD CONDITION WITH NO MAJOR SUBSIDENCE CRACKS OR GENERAL TRIP HAZARDS

WITNEY LANE

NATURAL STONE HEADSTONES IN RELATIVE GOOD CONDITION BUT WILL NEED IN DEPTH MEMORIAL STABILITY TESTING

EARTH BANKED UP TO BELOW COPING OF WALL

0.8m NATURAL STONE WALLING GOOD CONDITION

MATURE TREES BUTTING UP TO WITHIN 0.5m OF WALL. STABLE CONDITION WITH NO SIGNS OF ROOT DAMAGE

AREA OF CRACK ON CONCRETE PATHWAY. NO TRIP HAZARDS

1.2m NATURAL STONE WALLING

AREA OF OVERHANGING VEGETATION

1.2m NATURAL STONE WALLING GOOD CONDITION

1.2m NATURAL STONE WALLING GOOD CONDITION

0 10m 20m 30m

SCALE 1:200 @ A1

00 | 00.00.00 | X | X

CLIENT
LEAFIELD PARISH COUNCIL

PROJECT
PROPOSED CEMETERY EXTENSION
ST MICHAELS AND ALL ANGLES

TITLE
CHURCHYARD SURVEY PLAN

CDS
Cemeteries & Crematoria
Parks & Leisure
Environmental Solutions

The CDS Group
Building 51, Wrest Park
Silsoe, Bedfordshire
MK45 4HS
+44 (0)1525 864387
www.thecdsgroup.co.uk

Drawn by:	Approved by:	Drawing Status:
PC	JJS	ISSUED

Scale 1:200 @ A1
Sheet 1 of 1

Date: JAN 2020

CDS_LEA_FLD_04 | 00